


22-144 200 SHEETS











Figure 6







Figure 6b









Figure 8






Bode Response with Torque Disturbance at HDA Actuator




Positioner and HDA Response with Bang-Bang Seek Profile with Stiff Pin



Response Due to Torque Disturbance at HDA Actuator with Soft Material between HDA and Positioner


Tapaggagagana ng menag ayalam gigi a 💉 💡



Actuator and Positioner Response for Standard Bang-Bang Seek with Soft Material

Figure 13

the second of the second



Response for Torque Disturbance at Actuator with Eng Pin




Figure 15

Positioner and Actuator Response with Engineered Pin




Figure 16

properties and the second of the second